
110 Union Street, Suite 500, Seattle, Washington 98101-2038 Fax: 206-343-7522

Case No]
STATUS REPORT
, 19 <u>99</u> atm.
Responsible Person, Title
Gerald Brown EHAS mgr.
50. Scattle, WA 98134
were observed at the time of my inspection, with
e emissions documented from exhaust stack. ble fugitive dust emissions Raw Mill exit damper and in the Coal Mill se of the Visible emissions, been, and the preventative of prevent a recurrance are incidents described.
n (10) working days describing the necessary se to take, including a schedule, to address the Received by Signing this is not an admission of guilt

PSAPCA Form No. 70-182 (7/1/93) jrs

ASH GROVE CEMENT COMPANY



Elizabeth Gilpin Puget Sound Air Pollution Control Agency 110 Union Street, Suite 500 Seattle WA 98101-2038

Dear Ms. Gilpin:

Re: Compliance Status Report Dated 03/05/99

The following is further information as you requested on items noted on your March 5 visit.

G-Cooler Dust Collector:

On March 5, dust was noted coming from the stack for the G-Cooler dust collector. The collector was shut down immediately to cool for inspection. On March 7, the collector was inspected and repaired by the dust collector specialists. A few bad bags were found and these were replaced. The baghouse received a full bag changeout during our March kiln outage.

Raw Mill Exit Damper:

On March 5, fugitive dust was noted coming from the Raw Mill exit damper. The static pressure in the duct is controlled by the fan for the kiln baghouse. This was increased from -0.5 inches water gauge to -1.0 inches. This was to allow for more fluctuation in the raw mill system.

Coal Mill Hot Air Blower:

On March 5, fugitive dust was noted coming from the stack for the hot air blower for coal mill #2. The blower was shut down immediately. During our March kiln outage this was inspected and it was found that the ductwork was plugged. This was cleaned and the blower was put back on line without further incident.

Sincerely,

J. Trygve Grey Process Engineer Fax: 206-343-7522

Registration No	Case No.
COMPLIANCE	STATUS REPORT
Date of Report March 23	, 19 <u>99</u> at
Source Name	Responsible Person, Title
Ash Grove Cement Co.	Henrik Voldback Manager
Location	ð
3801 E. Marginal WA	y So. Seattle, WA. 98134
	were observed at the time of my inspection, with resp
During my inspection I noted the following	ng deficiencies: were reported.
Not 738 ! 5(b) > 70 on 12/22/98, 12/24/98, and 12/30/98	00 ppm NOX I Hour Average 12/25/98, 12/29/98)
	RECEIVED
	APR 0 2 1999
	AUUW-SEATTLE
	The second secon
	en (10) working days describing the necessary ose to take, including a schedule, to address the
Issued by: Way Man	Received by
2.21.90	~-P

ASH GROVE CEMENT COMPANY

"WESTERN REGION", 26, 1999

Elizabeth Gilpin Puget Sound Air Pollution Control Agency 110 Union Street, Suite 500 Seattle WA 98101-2038

Dear Ms. Gilpin:

Re: Compliance Status Report Dated 03/23/99

The following is further information as you requested on NOX emissions noted on out December CEM Report.

March 23, 1999:

The events dated from December 22 through December 30 were caused by interruptions to our tire burning system. The system had experience many "jams" of tires in the chutes and overloading of the belts. The result is a loss of fuel, increased oxygen to the system and the necessity to change fuels for the calciner quickly. All these cause the kiln to become unstable. At the time, the operator and those in the field work to restore the fuel supply and stabilize the kiln. The system includes a variable speed elevator which loads the tires one by one. The elevator at times was feeding the belt to quickly causing tires to overload the belt. Tuning was done to the controller for the elevator speed to eliminate this problem. The tires are pushed by a hydraulically operated ram into a double gate (airlock) which drops them into the kiln. If the hydraulics were acting slowly for these item, the ram would try to push a tire into the airlock before the top gate opened. Mechanical work was done to these gates during our April kiln outage to make the "ram" for pushing the tires into the airlock and the top gate of the airlock operate together. These events should be excused under WAC 173-400-107(6). The operator took quick action to reduce the NOX and we have worked and are continuing to work on the system.

Sincerely,

J. Trygve Grey Process Engineer

Registration No	Case No]
COMPLIANCE	STATUS REPORT
Date of Report April 14	, 19 <u>99</u> atm.
Source Name	Responsible Person, Title
Ash Grove Cement Co.	Gerald Brown EH & S
Location	
3801 E. Marginal Way So	Scattle, WA. 98134
No violations of PSAPCA's regulations we to the areas of the facility I inspected.	ere observed at the time of my inspection, with respec
During my inspection I noted the following	g deficiencies:
The following Violations	
February 0 1999 CEN	report:
Parte / Pollytant	Regulation/ Permit Condition
7/11	138 +3a > 1045 fpm 8fr.
5/7/99 CO NC	7381 #59 > 1045 ppm 8 Hr.
	7381 #56 > 700ppm 1 hr
2/15/99 NOX NC	7381 #56 > 700 ppm 1 fr.
	7381 #56 > 501 ppm 24 hr.
2/+/19 Opacity	
	Violations, These Violations
Will be Processed as Such	Under the 9/10/98 interim Policy
for CEms Civil Penalty for	olicy which has not been
No residente necessary: Expl Please submit a written report within ten	ahormon was provided in CEM report (10) working days describing the necessary
	se to take, including a schedule, to address the
a bove deficiencies.	
Toqued by: N	Pagained by
Issued by:	Received by
20.99 Feet Susin	

PUGET SOUND AIR POLLUTION CONTROL AGENCY RECEIVED

110 Union Street, Suite 500, Seattle, Washington 98101-2038

Fax: 206-343-7522

JUN 1 4 1999

Registration No. 1133 9

Case No. AGUVV-OCALILE

COMPLIANCE STATUS REPORT

Date of Report 6/7	, 19 <u>99</u> atm.
Source Name	Responsible Person, Title
Ash Grove Cement Co.	Henrik Voldback Mgr.
Location	
3801 E. Marginaly WA)	1 So. Sentle WA. 98134
No violations of PSAPCA's regulations respect to the areas of the facility I inspect	were observed at the time of my inspection, with ted.
During my inspection I noted the following	ng deficiencies:
	ins were reported on your
-DATE Pollytant Perm	it condition Actual
4/27 NOX NC 738	1 # 5(b) 1 hr 700 ppm/24 hr 50/pp. 875 ppm/553 pp
	were based on the 9/10/1998 civil penalty policy which approved and which is
	n (10) working days describing the necessary se to take, including a schedule, to address the
Issued by:	Received by
4	Signing this is not an admission of guilt

ASH GROVE CEMENT COMPANY



June 14, 1999

Elizabeth Gilpin Puget Sound Air Pollution Control Agency 110 Union Street, Suite 500 Seattle WA 98101-2038

Dear Ms. Gilpin:

Re: Compliance Status Report Dated 06/07/99

The following is further information as you requested Violations of our NOX limit on 4/27/99 and 4/28/99.

As reported in our April CEM, the kiln was restarted on April 25th after a long outage replacing brick. As often happens after long outages, the kiln feed we have in storage tends to segregate itself. This segregation can create long periods of time (several hours to several days) with kiln feed which is either harder than normal to burn or easier. We restarted the kiln and experienced a long period (two to three days) of high C₃S (hard to burn) feed. The operator during this period took normal measures to control the NO_X. These include operating a low oxygen levels in the kiln, keeping the feed as high as possible and some amount of sacrifice to the quality. While it is possible to burn the kiln slightly cooler and sacrifice quality, there reaches a point where this can cause the kiln to become unstable and cause the kiln to cycle and create more NO_X emissions.

Maintaining consistent chemistry of the kiln feed has always been and still remains a priority. Having consistent feed chemistry aids in the operating stability of the kiln and helps both maintain consistent product quality and lower the NO_X emissions during kiln operation. During the maintenance shutdown in the last half of March, much work was done to promote this. New airslide fabric was installed in our kiln feed blending silos. The valve between the blending and feed storage silos was redesigned to lessen the segregation of feed in the transfer of material between the two silos. Also in mid-May, the timing of the aeration was modified in the storage silos. This latest change cut the daily standard deviation of our kiln feed statistics by approximately 50%. While we still expect to see swings in our feed chemistry, we hope that the changes made in April and May have dramatically reduced the quantity and magnitude of these events.

Sincerely,

J. Trygve Grey Process Enginee

110 Union Street, Suite 500, Seattle, Washington 98101-2038

Fax: 206-343-7522

Registration No. 1339	Case No.
COMPLIANCE S	STATUS REPORT
TDate of Report 430	, 19 <u>99</u> atm.
	Responsible Person, Title Herrik Voldback, PHM3
Location 3801 E Marginal Wys Spattle, WA 98134	
No violations of PSAPCA's regulations respect to the areas of the facility I inspect	were observed at the time of my inspection, with ed. 9 CEM Reports generics: violations reported: 34 and ord NC 738 I # 5(b) 1.9.04(c)(1) not be subject to penalty 1.98 interim CEM civity h is not Board approved 25 say as explanation 25 port,
	se to take, including a schedule, to address the
· 2 · Issued II MM (Cf	Received by
PSAPCA Form No. 70-182 (7/1/93) jrs	

AGCS2M000521

110 Union Street, Suite 500, Seattle, Washington 98101-2038 Fax: 206-343-7522

of Report	, 19 <u>99</u> at
ce Name	Responsible Person, Title
sh Grove Cement Co.	Gerald Brown, Env. Mg
tion 3801 E Marginal Wy S Seattle, WA 98134	5
No violations of PSAPCA's reg	ulations were observed at the time of my inspection I inspected. — May 1999 CEM Report
During my inspection I noted the	
	×
Dlagge gubmit a varitten many	thin ten (10) working days describing the necessary
	ithin ten (10) working days describing the necessary propose to take, including a schedule, to address the

Fax: 206-343-7522

Registration No. 11339	Case No]
COMPLIANCE	STATUS REPORT
Date of Report October 29	, 19 <u>9 9</u> atm.
Source Name	Responsible Person, Title
Ash Grove Cement Co.	Henrik Voldback, Plat Myr
Location 3801 E. Marginal Way	50. Seattle, WA. 98134
	re observed at the time of my inspection, with respect ust 1999 CEM Report deficiencies: Violation 5 Seports
Date Pollutant	Standard
8/19/99 NOX	NOC 7381 \$ 5(b) 501 ppm NOX 24 hr.
This Violation will not per the Agency's 9/10/ Penatty policy which and is subject to ch	198 interim CEM CIVII
No response necessary	ras explanation provided
	(10) working days describing the necessary e to take, including a schedule, to address the
Issued by: PSAPCA Form No. 70-182 (7/1/93) jr	Received by

110 Union Štreet, Suite 500, Seattle, Washington 98101-2038 Fax: 206-343-7522

Registration No. 11339	Case No]
COMPLIANCE	STATUS REPORT
Date of Report November 1) , 19 <u>99</u> atm.
Ash Grove Cement Co,	Responsible Person, Title Henrik Voldback, PHM
Location 380 E Marginal Wy S Seattle, WA 98134	•
No violations of PSAPCA's regulations respect to the areas of the facility I inspect During my inspection, noted the following	
Miolation of NOX st on 9/6/99 in excess average.	of 7.00 ppm for 1 hour
This violation will per 9/10/98 interim not Bound approved	not be subject to penalty on CEM policy which is I + subject to change.
No response ne provided in CEM re	cessary as explanation
corrective action you have taken or proposabove deficiencies.	(10) working days describing the necessary se to take, including a schedule, to address the
Tissued by:	Received by

110 Union Street, Suite 500, Seattle, Washington 98101-2038 Fax: 206-343-7522

Date of Report <u>Vecember 15</u>	, 19 99 at
Source Name	Responsible Person, Title
Ash Grove Cement Co	Henrik Voldback, Plt N
Jeatle, WA.	nal Way So. 98134
No violations of PSAPCA's reg	rulations were observed at the time of my inspection
respect to the areas of the facility. Review of 40 During my inspection I noted the	our October CEM report for 1999, following deficiencies:
I observed 1	No Violations reported.
The state of the s	
1,1	
2 7	· · ·
•	
	N.,
	ithin ten (10) working days describing the necessary